

A perceptible reduction in the electrical line voltage supplied is usually caused by an excessive electrical demand on the electric utility or by an insufficient power-generation capability. This is also known as brown-down.

From:
<http://wiki.midibox.org/> - **MIDIbox**



Permanent link:
<http://wiki.midibox.org/doku.php?id=brownout&rev=1160904901>

Last update: **2007/11/17 18:38**