Generally a short-circuit on a PC board caused by solder joining two adjacent tracks.

From:
https://wiki.midibox.org/ - **MIDIbox**

Permanent link:
https://wiki.midibox.org/doku.php?id=bridge&rev=1160904901

Last update: **2007/11/17 18:37**