








To find midi devices known to work check the [midi_interface_whitelist](#).

Problems with SysEx transfers have been noticed with following MIDI interfaces:

| Vendor | Model | notes |
|------------|---|---|
| Access | Virus TI Polar  | Works unreliable for SysEx transfers under OS X (10.5). Suspected SysEx filtering. Plain MIDI sending/receiving seems OK. |
| Akai | MPD24  | |
| Behringer | BCA2000  | Works unreliable for SysEx transfers under Windows XP. Plain MIDI sending/receiving seems OK. |
| | BCR2000  | Works unreliable for SysEx transfers under OS X (10.5). Plain MIDI sending/receiving seems OK. |
| CME | VX 5  | Works unreliable for SysEx transfers under OS X (10.5). Suspected SysEx filtering. Plain MIDI sending/receiving seems OK. |
| E-MU | Xmidi 1x1 Tab | Works unreliable for SysEx transfers under Windows 7 64. See this thread for more details. |
| | Xmidi 2x2 | Same as above for Windows XP-64 bit. This thread describes the symptoms. |
| ESI | MIDIMATE | Works unreliable for SysEx transfers under Windows XP. Plain MIDI sending/receiving seems OK. |
| | RoMI/O II | In opposite to the RoMI/O I model this device uses native OS drivers and will therefore not be recognised by MIOS Studio. |
| JUstin | Midi USB | Unstable SysEx Transfers (checksum errors) under MacOS, probably also under Windows. |
| M-Audio | Audiophile USB  | |
| | Keystation Pro 88 | Works unreliable for SysEx transfers under Windows XP. Plain MIDI sending/receiving seems OK. |
| | MIDIsport 2x2 | Unstable SysEx transfers under MacOS 10.6 with most recent driver (last update: 2011) - was working stable years before, still works stable under Windows and Linux |
| NI | Kore 1 | Unstable SysEx transfers (sporadic checksum errors) under MacOS, probably also under Windows. |
| noname | MIDI USB Adapter | Sold at ebay for US\$7.99, also available at Maplin for £29.99 (what a difference...!) - incomplete SysEx transfers under MacOS! |
| Novation | Remote SL | Unstable SysEx transfers |
| Swisssonic | MIDI-USB 1x1 | Works unreliable for SysEx transfers under Windows (e.g. Buffer overrun messages during code upload) |
| Tascam | US-122 | Bytes get lost during SysEx transfer, even with the most recent windows driver version 3.3; model <u>US-122L</u> is OK! |
| Yamaha | UX256 | Bytes get lost during SysEx transfer under WinXP and 2000 (earlier versions not tested), even with most recent MIDI drivers (Yamaha <i>universal</i> drivers) |

Devices marked with a  should be confirmed to be not working by a second user. If you can

confirm that a device isn't suited for MB-usage, edit this page and remove the corresponding .



When adding to this list, try to keep it sorted alphabetically, please.

From:

<http://wiki.midibox.org/> - **MIDIbox**

Permanent link:

http://wiki.midibox.org/doku.php?id=midi_interface_blacklist&rev=1353387922

Last update: **2012/11/20 05:05**

