


















To find midi devices known to work check the [midi_interface_whitelist](#).

Problems with SysEx transfers have been noticed with following MIDI interfaces:

| Vendor | Model | notes |
|-------------------|--|---|
| Access | Virus TI Polar  | Works unreliable for SysEx transfers under OS X (10.5). Suspected SysEx filtering. Plain MIDI sending/receiving seems OK. |
| Akai | MPD24  | |
| Behringer | BCA2000  | Works unreliable for SysEx transfers under Windows XP. Plain MIDI sending/receiving seems OK. |
| Behringer | FCA1616  | No SysEx activity on Mac OS X and Windows 7. |
| | BCR2000  | Works unreliable for SysEx transfers under OS X (10.5) and Windows (e.g. Vista). Plain MIDI sending/receiving seems OK. |
| Cakewalk/Roland | UM-1G | See this post and this info @ Roland for details. |
| CME | VX 5  | Works unreliable for SysEx transfers under OS X (10.5). Suspected SysEx filtering. Plain MIDI sending/receiving seems OK. |
| Conrad Electronic | UA0037 | Bytes get lost during SysEx transfer under OSX and WinXP |
| E-MU | Xmidi 1x1 Tab | Works unreliable for SysEx transfers under Windows 7 64. See this thread for more details. |
| | Xmidi 2x2 | Same as above for Windows XP-64 bit. This thread describes the symptoms. |
| ESI | MIDIMATE  | Works unreliable for SysEx transfers under Windows XP. Plain MIDI sending/receiving seems OK. |
| | RoMI/O II | In opposite to the RoMI/O I model this device uses native OS drivers and will therefore not be recognised by MIOS Studio. |
| iConnectivity | mio | Midi Out will not work through an LPC17 unless R21 & R26 are changed to 47 Ohm. See updated schematic and BOM in the mbhp_core_lpc17 page. |
| JUstin | Midi USB | Unstable SysEx Transfers (checksum errors) under MacOS, probably also under Windows. |
| M-Audio | Audiophile USB  | |
| | Keystation Pro 88  | Works unreliable for SysEx transfers under Windows XP. Plain MIDI sending/receiving seems OK. |
| | MIDIsport 2x2 | Unstable SysEx transfers under MacOS 10.6 with most recent driver (last update: 2011) - was working stable years before, still works stable under Windows and Linux |
| NI | Kore 1  | Unstable SysEx transfers (sporadic checksum errors) under MacOS, probably also under Windows. |
| <i>noname</i> | MIDI USB Adapter | Sold at ebay for US\$7.99, also available at Maplin for £29.99 (what a difference...!) - incomplete SysEx transfers under MacOS! |
| Novation | Remote SL  | Unstable SysEx transfers |

| Vendor | Model | notes |
|------------|--|---|
| Novation | Remote SL37 limited edition | Unstable MIDI, manifests as core resets, on Mac OS X. |
| Swisssonic | MIDI-USB 1×1  | Works unreliable for SysEx transfers under Windows (e.g. Buffer overrun messages during code upload) |
| Tascam | US-122  | Bytes get lost during SysEx transfer, even with the most recent windows driver version 3.3; model <u>US-122L</u> is OK! |
| Yamaha | UX256 |  Bytes get lost during SysEx transfer under WinXP and 2000 (earlier versions not tested), even with most recent MIDI drivers (Yamaha <i>universal</i> drivers) |

Devices marked with a  should be confirmed to be not working by a second user. If you can confirm that a device isn't suited for MB-usage, edit this page and remove the corresponding .

 When adding to this list, try to keep it sorted alphabetically, please.

From:
<https://wiki.midibox.org/> - **MIDIbox**

Permanent link:
https://wiki.midibox.org/doku.php?id=midi_interface_blacklist&rev=1396301361

Last update: **2014/03/31 21:29**

