

Problems with SysEx transfers have been noticed with following MIDI interfaces:

Soundblaster Audigy: some older driver versions don't work reliable, use the latest one

Tascam US-122: bytes get lost during SysEx transfer, even with the most recent windows driver version 3.3

Yamaha UX256: bytes get lost during SysEx transfer under WinXP and 2000 (earlier versions not tested), even with most recent MIDI drivers (Yamaha *universal* drivers)

ESI MIDIMATE: works unreliable for SysEx transfers under Windows XP. Plain MIDI sending/receiving seems OK.

ESI Rom I/O II: this device it's driver free, as the USB audio support in the OS automatically supports it (win & mac) but MIOS Studio don't recognize the MIDI Ports of it. The device Rom I/O 1st release work fine instead, it come with own drivers.

Behringer BCA2000: works unreliable for SysEx transfers under Windows XP. Plain MIDI sending/receiving seems OK. See the [Re: Impossible to upload MIOS](#) thread for details.

M-Audio Keystation Pro 88: works unreliable for SysEx transfers under Windows XP. Plain MIDI sending/receiving seems OK. See the [Re: Impossible to upload MIOS](#) thread for details.

From:
<https://wiki.midibox.org/> - **MIDIbox**

Permanent link:
https://wiki.midibox.org/doku.php?id=midi_interface_blacklist&rev=1207294662

Last update: **2008/11/17 17:58**

